

1109 ROMA MALE HOSE PORT

FITTINGS FOR AGRICULTURAL-INDUSTRIAL MAINTENANCE > STANDARD FITTINGS IN YELLOW BRASS

YELLOW BRASS FITTING CONICAL BSP MALE THREADED HOSE FITTING 'ROMA' TYPE

331109006-01/8 331109006-01/4 331109006-03/8 331109006-01/2	6-1/8" 6-1/4" 6-3/8" 6-1/2" 8-1/8"	50 50 50 50	from BARRA from BARRA from BARRA
331109006-03/8	6-3/8"	50	from BARRA
	6-1/2"		
331109006-01/2		50	from DADDA
	8-1/8"		from BARRA
331109008-01/8		50	from BARRA
331109008-01/4	8-1/4"	50	from BARRA
331109008-03/8	8-3/8"	50	from BARRA
331109008-01/2	8-1/2"	50	from BARRA
331109010-01/8	10-1/8"	50	from BARRA
331109010-01/4	10-1/4"	50	from BARRA
331109010-03/8	10-3/8"	40	from BARRA
331109010-01/2	10-1/2"	50	from BARRA
331109013-01/4	13-1/4"	50	from BARRA
331109013-03/8	13-3/8"	30	from BARRA
331109013-01/2	13-1/2"	50	from BARRA
331109013-03/4	13-3/4"	30	from STAMPO
331109015-03/8	15-3/8"	30	from BARRA
331109015-01/2	15-1/2"	50	from BARRA
331109016-01/2	16-1/2"	50	from BARRA
331109016-03/4	16-3/4"	30	from STAMPO
331109018-01/2	18-1/2"	40	from BARRA
331109018-03/4	18-3/4"	30	from STAMPO
331109020-01/2	20-1/2"	40	from BARRA
331109020-03/4	20-3/4"	25	from STAMPO
331109020-1	20-1"	30	from STAMPO
331109022-03/4	22-3/4"	25	from STAMPO

331109025-03/4	25-3/4"	15	from STAMPO
331109025-1	25-1"	30	from STAMPO
331109027-1	27-1"	30	from STAMPO
331109030-1	30-1"	25	from STAMPO
331109030-11/4	30-1"1/4	20	from STAMPO
331109032-1	32-1"	20	from STAMPO
331109032-11/4	32-1"1/4	20	from STAMPO
331109035-11/4	35-1"1/4	15	from STAMPO
331109038-11/2	38-1"1/2	15	from STAMPO
331109040-11/4	40-1"1/4	12	from STAMPO
331109040-11/2	40-1"1/2	12	from STAMPO
331109045-11/2	45-1"1/2	10	from STAMPO
331109050-11/2	50-1"1/2	10	from STAMPO
331109051-2	51-2"	8	from STAMPO
331109060-2	60-2"	5	from STAMPO
331109060-21/2	60-2"1/2	8	from STAMPO
331109063-21/2	63-2"1/2	8	from STAMPO
331109070-21/2	70-2"1/2	5	from STAMPO
331109076-3	76-3"	5	from STAMPO
331109080-3	80-3"	2	from STAMPO
331109100-4	100-4"	2	from FUSION
331109100-4	102-4"	2	from FUSION