





















































<i>Tube to Tube Union</i>		
Union SU		14
Union Elbow SL		15
Reducing Union SUR		16,17
Union Tee ST		18
Union Cross SX		19
Reducing Union Tee STR		20, 21
Bulkhead Union SUB		22
<i>Tube to Male Pipe</i>		
Male Connector SMC-N		23
Male Connector SMC-R		24
Thermocouple Connector SMCT		24
Male Connector for Bonded Seal SMC-G		25
Male Connector for Metal Gasket SOM		27,28
Bulkhead Male Connector SMCB		29
45° Male Elbow SLBM		29
Male Elbow SLM		30, 31
Male Run Tee STRM		32, 33
Male Branch Tee STBM		34, 35

<i>Tube to Female Pipe</i>		
Female Connector SCF		36, 37
Gauge Connector SCG		38
Bulkhead Female Connector SCBF		38
Female Elbow SLF		39
Female Run Tee STRF		40
Female Branch Tee STBF		41
<i>Stub Tube Connector</i>		
Reducer SR		42, 43
Bulkhead Adapter SAB		44
Male Adapter SAM		44, 45
Female Adapter SAF		46
Female Adapter SAG		47
Port Connector SCP		48
Reducing Port Connector SCRCP		48
<i>Tube to AN Tube</i>		
AN Union SUA		49
AN Bulkhead Union SUBA		49
AN Adapter SAA		49
<i>Tube to SAE O-Ring Seal</i>		
SAE Male Connector SMCS		51
Positionable SAE Male Elbow SLS		51

Positionable 45° SAE Male Elbow SLBS		52
Positionable SAE Male Run Tee STRS		52
Positionable SAE Male Branch Tee STBS		52
O-Seal Straight Thread Connector SCOS		54
O-Seal Pipe Thread Connector SCOP		54
<i>Tube to Weld End</i>		
Male Pipe Weld Connector SCW		55
Male Pipe Weld Elbow SLW		56
Tube Socket Weld Connector SCSW		56
Tube Socket Weld Elbow SLSW		56
Welding Bulkhead Union SBUW		57
<i>Plug and Cap</i>		
Plug SP		58
Cap SC		58
<i>Spare Parts</i>		
Tube Insert SI		59
Nut SN		59
Front Ferrule SFF		60
Back Ferrule SFB		60
Ferrule Set SFS10		60